



STRÄHLE
GUMMIFORMTECHNIK GMBH


GUMMI-METALL-VERBINDUNGEN

| TYP A | | | | | | | | | | | | | | |
|--------------|-----|----|----------------|--|----|----|-----|----------------|--|-----|----|-----|-------|--|
| D | H | d | h | | D | H | d | h | | D | H | d | h | |
| 15 | 6 | M4 | 6,8,10,12 | | 30 | 30 | M8 | 13,15,18,20,23 | | 60 | 30 | M10 | 20,33 | |
| 15 | 8 | M4 | 6,8,10,12 | | 30 | 40 | M8 | 13,15,18,20,23 | | 60 | 40 | M10 | 20,33 | |
| 15 | 15 | M4 | 6,8,10,12 | | 40 | 25 | M8 | 20,23 | | 60 | 50 | M10 | 20,33 | |
| 15 | 20 | M4 | 6,8,10,12 | | 40 | 30 | M8 | 20,23 | | 60 | 55 | M10 | 20,33 | |
| 18 | 8,5 | M6 | 10 | | 40 | 35 | M8 | 20,23 | | 60 | 30 | M12 | 33,38 | |
| 20 | 8 | M6 | 8,10,12,15,18 | | 40 | 40 | M8 | 20,23 | | 60 | 40 | M12 | 33,38 | |
| 20 | 15 | M6 | 8,10,12,15,18 | | 40 | 25 | M10 | 20,28 | | 60 | 50 | M12 | 33,38 | |
| 20 | 20 | M6 | 8,10,12,15,18 | | 40 | 30 | M10 | 20,28 | | 60 | 50 | M12 | 33,38 | |
| 20 | 25 | M6 | 8,10,12,15,18 | | 40 | 35 | M10 | 20,28 | | 75 | 40 | M12 | 33,38 | |
| 20 | 30 | M6 | 8,10,12,15,18 | | 40 | 40 | M10 | 20,28 | | 75 | 50 | M12 | 33,38 | |
| 25 | 15 | M6 | 10,12,15,18 | | 50 | 20 | M10 | 20,25,28,33 | | 75 | 55 | M12 | 33,38 | |
| 25 | 20 | M6 | 10,12,15,18 | | 50 | 25 | M10 | 20,25,28,33 | | 100 | 40 | M16 | 42 | |
| 25 | 25 | M6 | 10,12,15,18 | | 50 | 30 | M10 | 20,25,28,33 | | 100 | 50 | M16 | 42 | |
| 25 | 30 | M6 | 10,12,15,18 | | 50 | 35 | M10 | 20,25,28,33 | | 100 | 55 | M16 | 42 | |
| 30 | 15 | M8 | 13,15,18,20,23 | | 50 | 40 | M10 | 20,25,28,33 | | 100 | 60 | M16 | 42 | |
| 30 | 20 | M8 | 13,15,18,20,23 | | 50 | 45 | M10 | 20,25,28,33 | | 100 | 75 | M16 | 42 | |
| 30 | 25 | M8 | 13,15,18,20,23 | | 50 | 50 | M10 | 20,25,28,33 | | | | | | |

| TYP B | | | | | | | | | | | | | | | | | |
|--------------|----|----|----------------|---|--|----|----|-----|-------------|---|--|-----|----|-----|-------|----|--|
| D | H | d | h | i | | D | H | d | h | i | | D | H | d | h | i | |
| 15 | 15 | M4 | 6,8,10,12 | 4 | | 40 | 25 | M8 | 20,23 | 7 | | 60 | 30 | M10 | 20,33 | 8 | |
| 15 | 20 | M4 | 6,8,10,12 | 4 | | 40 | 30 | M8 | 20,23 | 7 | | 60 | 40 | M10 | 20,33 | 8 | |
| 20 | 15 | M6 | 8,10,12,15,18 | 5 | | 40 | 35 | M8 | 20,23 | 7 | | 60 | 50 | M10 | 20,33 | 8 | |
| 20 | 20 | M6 | 8,10,12,15,18 | 5 | | 40 | 40 | M8 | 20,23 | 7 | | 60 | 55 | M10 | 20,33 | 8 | |
| 20 | 25 | M6 | 8,10,12,15,18 | 5 | | 40 | 25 | M10 | 20,28 | 8 | | 60 | 30 | M12 | 33,38 | 10 | |
| 20 | 30 | M6 | 8,10,12,15,18 | 5 | | 40 | 30 | M10 | 20,28 | 8 | | 60 | 40 | M12 | 33,38 | 10 | |
| 25 | 15 | M6 | 10,12,15,18 | 5 | | 40 | 35 | M10 | 20,28 | 8 | | 60 | 50 | M12 | 33,38 | 10 | |
| 25 | 20 | M6 | 10,12,15,18 | 5 | | 40 | 40 | M10 | 20,28 | 8 | | 60 | 55 | M12 | 33,38 | 10 | |
| 25 | 25 | M6 | 10,12,15,18 | 5 | | 50 | 20 | M10 | 20,25,28,33 | 8 | | 75 | 40 | M12 | 33,38 | 10 | |
| 25 | 30 | M6 | 10,12,15,18 | 5 | | 50 | 25 | M10 | 20,25,28,33 | 8 | | 75 | 50 | M12 | 33,38 | 10 | |
| 30 | 20 | M8 | 13,15,18,20,23 | 6 | | 50 | 30 | M10 | 20,25,28,33 | 8 | | 75 | 55 | M12 | 33,38 | 10 | |
| 30 | 25 | M8 | 13,15,18,20,23 | 6 | | 50 | 35 | M10 | 20,25,28,33 | 8 | | 100 | 40 | M16 | 42 | 13 | |
| 30 | 30 | M8 | 13,15,18,20,23 | 6 | | 50 | 40 | M10 | 20,25,28,33 | 8 | | 100 | 50 | M16 | 42 | 13 | |
| 30 | 40 | M8 | 13,15,18,20,23 | 6 | | 50 | 45 | M10 | 20,25,28,33 | 8 | | 100 | 55 | M16 | 42 | 13 | |
| | | | | | | | | | | | | 100 | 60 | M16 | 42 | 13 | |
| | | | | | | | | | | | | 100 | 75 | M16 | 42 | 13 | |


Wertstrasse 10
73257 Köngen/Neckar
Tel. 07024 / 98337-0
Fax 07024 / 98337-20
info@straehle-gummiformtechnik.de

TYP C




| D | H | d | i | D | H | d | i | D | H | d | i | D | H | d | i |
|----|----|----|---|----|----|-----|---|----|----|-----|----|-----|----|-----|----|
| 15 | 15 | M4 | 4 | 30 | 30 | M8 | 6 | 50 | 25 | M10 | 8 | 60 | 50 | M12 | 10 |
| 20 | 15 | M6 | 5 | 30 | 40 | M8 | 6 | 50 | 30 | M10 | 8 | 60 | 55 | M12 | 10 |
| 20 | 20 | M6 | 5 | 40 | 25 | M8 | 7 | 50 | 35 | M10 | 8 | 75 | 40 | M12 | 10 |
| 20 | 25 | M6 | 5 | 40 | 30 | M8 | 7 | 50 | 40 | M10 | 8 | 75 | 50 | M12 | 10 |
| 20 | 30 | M6 | 5 | 40 | 35 | M8 | 7 | 50 | 45 | M10 | 8 | 75 | 55 | M12 | 10 |
| 25 | 15 | M6 | 5 | 40 | 40 | M8 | 7 | 60 | 30 | M10 | 8 | 90 | 55 | M12 | 10 |
| 25 | 20 | M6 | 5 | 40 | 25 | M10 | 8 | 60 | 40 | M10 | 8 | 100 | 40 | M16 | 13 |
| 25 | 25 | M6 | 5 | 40 | 30 | M10 | 8 | 60 | 50 | M10 | 8 | 100 | 50 | M16 | 13 |
| 25 | 30 | M6 | 5 | 40 | 35 | M10 | 8 | 60 | 55 | M10 | 8 | 100 | 55 | M16 | 13 |
| 30 | 20 | M8 | 6 | 40 | 40 | M10 | 8 | 60 | 30 | M12 | 10 | 100 | 60 | M16 | 13 |
| 30 | 25 | M8 | 6 | | | | | 60 | 40 | M12 | 10 | 100 | 75 | M16 | 13 |

TYP D



| D | H | d | h | D | H | d | h | D | H | d | h |
|----|------|----|---------------|----|----|-----|----------------|-----|----|-----|-------------|
| 15 | 6 | M4 | 6,8,10,12 | 30 | 15 | M8 | 13,15,18,20,23 | 50 | 35 | M10 | 20,25,28,33 |
| 15 | 7 | M4 | 6,8,10,12 | 30 | 17 | M8 | 13,15,18,20,23 | 50 | 40 | M10 | 20,25,28,33 |
| 15 | 8 | M4 | 6,8,10,12 | 30 | 20 | M8 | 13,15,18,20,23 | 50 | 45 | M10 | 20,25,28,33 |
| 15 | 15 | M4 | 6,8,10,12 | 30 | 22 | M8 | 13,15,18,20,23 | | | | |
| 15 | 20 | M4 | 6,8,10,12 | 30 | 25 | M8 | 13,15,18,20,23 | 60 | 30 | M10 | 20,33 |
| 18 | 7,5 | M6 | 10 | 30 | 30 | M8 | 13,15,18,20,23 | 60 | 40 | M10 | 20,33 |
| 20 | 13,5 | M6 | 8,10,12,15,18 | 30 | 40 | M8 | 13,15,18,20,23 | 60 | 50 | M10 | 20,33 |
| 20 | 15 | M6 | 8,10,12,15,18 | 40 | 20 | M8 | 20,23 | 60 | 55 | M10 | 20,33 |
| 20 | 20 | M6 | 8,10,12,15,18 | 40 | 25 | M8 | 20,23 | 60 | 30 | M12 | 33,38 |
| 20 | 25 | M6 | 8,10,12,15,18 | 40 | 27 | M8 | 20,23 | 60 | 40 | M12 | 33,38 |
| 20 | 30 | M6 | 8,10,12,15,18 | 40 | 30 | M8 | 20,23 | 60 | 50 | M12 | 33,38 |
| 25 | 25 | M6 | 5 | 40 | 35 | M8 | 20,23 | 60 | 55 | M12 | 33,38 |
| 25 | 30 | M6 | 5 | 40 | 40 | M8 | 20,23 | 75 | 30 | M12 | 33,38 |
| 25 | 8 | M6 | 10,12,15,18 | 40 | 20 | M10 | 20,28 | 75 | 40 | M12 | 33,38 |
| 25 | 10 | M6 | 10,12,15,18 | 40 | 25 | M10 | 20,28 | 75 | 50 | M12 | 33,38 |
| 25 | 12 | M6 | 10,12,15,18 | 40 | 27 | M10 | 20,28 | 75 | 55 | M12 | 33,38 |
| 25 | 15 | M6 | 10,12,15,18 | 40 | 30 | M10 | 20,28 | | | | |
| 25 | 17 | M6 | 10,12,15,18 | 40 | 35 | M10 | 20,28 | 100 | 30 | M16 | 42 |
| 25 | 20 | M6 | 10,12,15,18 | 40 | 40 | M10 | 20,28 | 100 | 40 | M16 | 42 |
| 25 | 25 | M6 | 10,12,15,18 | 50 | 21 | M10 | 20,25,28,33 | 100 | 50 | M16 | 42 |
| 25 | 30 | M6 | 10,12,15,18 | 50 | 25 | M10 | 20,25,28,33 | 100 | 55 | M16 | 42 |
| | | | | 50 | 30 | M10 | 20,25,28,33 | 100 | 60 | M16 | 42 |
| | | | | | | | | 100 | 75 | M16 | 42 |

TYP E



| D | H | d | i | D | H | d | i | D | H | d | i | D | H | d | i |
|----|------|----|---|----|----|-----|---|----|----|-----|---|-----|----|-----|----|
| 15 | 8 | M4 | 4 | 30 | 15 | M8 | 6 | 40 | 27 | M10 | 8 | 60 | 30 | M12 | 10 |
| 15 | 15 | M4 | 4 | 30 | 17 | M8 | 6 | 40 | 30 | M10 | 8 | 60 | 40 | M12 | 10 |
| 15 | 20 | M4 | 4 | 30 | 20 | M8 | 6 | 40 | 35 | M10 | 8 | 60 | 50 | M12 | 10 |
| | | | | 30 | 22 | M8 | 6 | 40 | 40 | M10 | 8 | 60 | 55 | M12 | 10 |
| 20 | 13,5 | M6 | 5 | 30 | 25 | M8 | 6 | | | | | 75 | 30 | M12 | 8 |
| 20 | 15 | M6 | 5 | 30 | 30 | M8 | 6 | 50 | 21 | M10 | 8 | 75 | 40 | M12 | 8 |
| 20 | 20 | M6 | 5 | 30 | 40 | M8 | 6 | 50 | 25 | M10 | 8 | 75 | 50 | M12 | 8 |
| 20 | 25 | M6 | 5 | 40 | 20 | M8 | 7 | 50 | 30 | M10 | 8 | 75 | 55 | M12 | 8 |
| 20 | 30 | M6 | 5 | 40 | 25 | M8 | 7 | 50 | 35 | M10 | 8 | 90 | 55 | M12 | 8 |
| | | | | 40 | 27 | M8 | 7 | 50 | 40 | M10 | 8 | 100 | 30 | M16 | 13 |
| 25 | 10 | M6 | 5 | 40 | 30 | M8 | 7 | 50 | 45 | M10 | 8 | 100 | 40 | M16 | 13 |
| 25 | 12 | M6 | 5 | 40 | 35 | M8 | 7 | 60 | 30 | M10 | 8 | 100 | 50 | M16 | 13 |
| 25 | 15 | M6 | 5 | 40 | 40 | M8 | 7 | 60 | 40 | M10 | 8 | 100 | 55 | M16 | 13 |
| 25 | 17 | M6 | 5 | 40 | 20 | M10 | 8 | 60 | 50 | M10 | 8 | 100 | 60 | M16 | 13 |
| 25 | 20 | M6 | 5 | 40 | 25 | M10 | 8 | 60 | 55 | M10 | 8 | 100 | 75 | M16 | 13 |

Wir fertigen auch Gummi-Metallverbindungen sowie Gummiformteile nach Zeichnungen und Angaben. Bitte fragen Sie bei uns an.

Wertstrasse 10
73257 Köngen/Neckar
Tel. 07024 / 98337-0
Fax 07024 / 98337-20
info@strahle-gummiformtechnik.de